

IHC CDF Dredge Project : Air Monitoring Alarm Response Log

Air Monitoring Station: M1 M2 M3 M4 Dock

Air Monitoring Instrument:

Cerex Unit (Naphthalene) Thermo Unit (Particles) PID Monitor

Date & Time of alarm: 10/02/16 1:30AM

Email sent to site Technician? Yes or No

Technician responded to the alarm; Scott Peterson

1. Was dredging occurring at the time of the alarm? Yes or No)
2. Alarm caused by:

<input type="checkbox"/>	Loss of Power
<input type="checkbox"/>	Loss of Radio Communication
<input type="checkbox"/>	Out of Calibration
<input type="checkbox"/>	UV Alignment
<input type="checkbox"/>	Blockage in Air Tube
<input checked="" type="checkbox"/>	Air Quality
<input checked="" type="checkbox"/>	Other: Unknown

3. Corrective Actions taken? (Yes or No)
4. Dredging suspended? (Yes or No)
5. Alarm logged in air monitoring action spreadsheet? Yes or No)

Description of Action Taken:

Air units calibrations were checked and with-in toloarnce.